

## Collaboration sees improvement to road leading to ArcelorMittal Newcastle works

ArcelorMittal South Africa Newcastle works recently collaborated with the Department of Roads in Kwa-Zulu Natal to repair a stretch of roadway leading up to the works that had deteriorated significantly due to the vast amount of rain experienced as of late.

This stretch of road had become extremely hazardous as vehicles, including heavy vehicles were driving onto the opposite side of the road in the face of oncoming traffic to avoid the potholes.

ArcelorMittal South Africa supplied a load of tar as well as five variously skilled employees over a period of seven days to ensure that the road was returned to its level best.



**Before**



**After**